

ABSTRACT OF THE DISCLOSURE

A method for manufacturing lustrous rubber includes:

Step 1: choose rubber of different colors;

Step 2: add 1-100g pearl pigment to each 1kg rubber;

5 Step 3: mix the above combination;

Step 4: cool the above mixture for 2 hours;

Step 5: cut the above mixture into grains;

Step 6: vulcanize and extrude the above grains for 4 minutes 30
seconds to 5 minutes 30 seconds;

10 Step 7: the lustrous rubber is finished.

Thus, lustrous colorful rubber can be manufactured through the
above 7 steps, and figures can be produced too.